

## 2. Części zamienne do HILTI

Kod CH 121		Simerring łożyska	Kod CH 131		Element amortyzujący	Kod CH 141		Wirnik z łożyskiem
Cena 10,89			Cena 43,56		18035 POZ 126	Cena 228,72		16005K POZ 5
Szt.		20003M	Szt.	202306		Szt.	203263	
Kod CH 122		Łożysko	Kod CH 132		Podkładka	Kod CH 142		Zębatka
Cena 47,92			Cena 38,12		18036 POZ 136	Cena 62,62		17012 POZ 96
Szt.	30275	POZ 32	Szt.	22307		Szt.	203159	
Kod CH 123		Wentylator	Kod CH 133		Pierścień rozprężny	Kod CH 143		Zębatka
Cena 21,78			Cena 4,35		18065 POZ 132	Cena 62,62		17013 POZ 96
Szt.	277083	16032 POZ 34	Szt.	202180		Szt.	203259	
Kod CH 124		Wirnik z łożyskiem	Kod CH 134		Walec	Kod CH 144		Zębatka mała
Cena 245,06			Cena 10,89		18004 POZ 110	Cena 40,84		17011 POZ 114
Szt.	277155	16011K POZ 5	Szt.	72139		Szt.	202135	
Kod CH 125		Wentylator	Kod CH 135		Uchwyt	Kod CH 145		Sworzeń tłoka
Cena 20,68			Cena 271,14		18114 POZ 122	Cena 15,29		18116
Szt.	316002	16015 POZ 34	Szt.	202764		Szt.		
Kod CH 126		Wirnik z łożyskiem	Kod CH 136		Pokrywa	Kod CH 146		Korbowód
Cena 255,95			Cena 10,89		18037 POZ 147	Cena 43,58		18034
Szt.	316172	16024K POZ 5	Szt.	206308		Szt.		
Kod CH 127		Simerring	Kod CH 137		Uchwyt	Kod CH 147		Uchwyt
Cena 8,16	HILTI TE 54, TE 55, TE 504, TE 505		Cena 103,46	HILTI TE 54, TE 55, TE 504, TE 505		Cena 408,43		18021 POZ 57
Szt.	201141	2032588 POZ 101	Szt.	203133	19015 POZ 20	Szt.	74102	
Kod CH 128		Łożysko	Kod CH 138		Wentylator	Kod CH 148		Walce
Cena 45,78	HILTI TE 54, TE 55, TE 504, TE 505		Cena 21,78	HILTI TE 54, TE 55, TE 504, TE 505		Cena 10,89		18004 POZ 73
Szt.	202122	11002 POZ 142	Szt.	202208	16032 POZ 34	Szt.	72139	
Kod CH 129		Oring 20 x 3,53	Kod CH 139		Simerring łożyska	Kod CH 149		Sworzeń
Cena 7,08	HILTI TE 54, TE 55, TE 504, TE 505		Cena 10,89		20003M	Cena 9,79		18010AL POZ 33
Szt.	72416	21011 POZ 13	Szt.			Szt.	72053	
Kod CH 130		Oring	Kod CH 140		Łożysko	Kod CH 150		Sworzeń
Cena 13,61	HILTI TE 54, TE 55, TE 504, TE 505		Cena 47,92	HILTI TE 54, TE 55, TE 504, TE 505		Cena 9,79		18010 POZ 33
Szt.	202172	21014 POZ 149	Szt.	30275	11001 POZ 32	Szt.	72053	

## 2. Części zamienne do HILTI

Kod CH 151	<b>HILTI TE 42 TE 52</b> 	Korbowód 18062AL POZ 16	Kod CH 161	<b>HILTI TE 60, TE 72</b> 	Sworzeń 18010AL POZ 33	Kod CH 171	<b>HILTI TE 60, TE 72</b> 	Simering 15/16x24 x 4,5/8 mm 20002 POZ 117
Cena 29,95			Cena 13,61			Cena 10,89		
Szt.	72052		Szt.	72053		Szt.	30278	
Kod CH 152	<b>HILTI TE 42 TE 52</b> 	Korbowód 18062 POZ 16	Kod CH 162	<b>HILTI TE 60, TE 72</b> 	Sworzeń 18010AL POZ 33	Kod CH 172	<b>HILTI TE 60, TE 72</b> 	Tulejka POZ 40
Cena 51,73			Cena 16,34			Cena 65,35		
Szt.	72052		Szt.	72053		Szt.		
Kod CH 153	<b>HILTI TE 42 TE 52</b> 	Oring 21001 POZ 86	Kod CH 163	<b>HILTI TE 60, TE 72</b> 	Tłok wzbudzający 18011 POZ 32	Kod CH 173	<b>HILTI TE 60, TE 72</b> 	Tulejka 18008 POZ 49
Cena 7,08			Cena 52,09			Cena 16,34		
Szt.	72416		Szt.	72109		Szt.	72304	
Kod CH 154	<b>HILTI TE 42 TE 52</b> 	Tłok 18011 POZ 68	Kod CH 164	<b>HILTI TE 60, TE 72</b> 	Oring 20 x 3,53 21001 POZ 119	Kod CH 174	<b>HILTI TE 60, TE 72</b> 	Podkładka 18016 POZ 55
Cena 59,90			Cena 59,90			Cena 16,34		
Szt.	72109		Szt.	72416		Szt.	72307	
Kod CH 155	<b>HILTI TE 42 TE 52</b> 	Sprężyny amortyzujące 18090	Kod CH 165	<b>HILTI TE 60, TE 72</b> 	Korbowód 18062AL POZ 22	Kod CH 175	<b>HILTI TE 60, TE 72</b> 	Podkładka 18009
Cena 46,83			Cena 29,95			Cena 8,16		
Szt.	74113		Szt.	72052		Szt.	72308	
Kod CH 156	<b>HILTI TE 42 TE 52</b> 	Zębatka 17005 POZ 72	Kod CH 166	<b>HILTI TE 60, TE 72</b> 	Korbowód 18062 POZ 22	Kod CH 176	<b>HILTI TE 60, TE 72</b> 	Pierścień sprężynujący 18007 POZ 52
Cena 87,13			Cena 51,73			Cena 27,23		
Szt.	74124		Szt.	72052		Szt.	72315	
Kod CH 157	<b>HILTI TE 42 TE 52</b> 	Zębatka 17006 POZ 75	Kod CH 167	<b>HILTI TE 60, TE 72</b> 	Wałek korbowy 17003 POZ 90	Kod CH 177	<b>HILTI TE 60, TE 72</b> 	Pierścień uszczelniający 18013 POZ 4
Cena 76,24			Cena 326,74			Cena 65,35		
Szt.	74227		Szt.	72205		Szt.	72182	
Kod CH 158	<b>HILTI TE 42 TE 52</b> 	Uchwyt 19001	Kod CH 168	<b>HILTI TE 60, TE 72</b> 	Nakrętka 17004 POZ 91	Kod CH 178	<b>HILTI TE 60, TE 72</b> 	Uchwyt 18003 POZ 85
Cena 54,46			Cena 13,61			Cena 245,06		
Szt.			Szt.	72206		Szt.	72237	
Kod CH 159	<b>HILTI TE 42 TE 52</b> 	Opaska 19002	Kod CH 169	<b>HILTI TE 60, TE 72</b> 	Tłok bijący 18014 POZ 46	Kod CH 179	<b>HILTI TE 60, TE 72</b> 	Walce 18004 POZ 54
Cena 49,01			Cena 59,90			Cena 10,89		
Szt.			Szt.	72341		Szt.	72139	
Kod CH 160	<b>HILTI TE 42 TE 52</b> 	Śruba 19003	Kod CH 170	<b>HILTI TE 60, TE 72</b> 	Bijak 18005 POZ 42	Kod CH 180	<b>HILTI TE 60, TE 72</b> 	Pokrywa 18001 POZ 58
Cena 19,05			Cena 87,13			Cena 10,89		
Szt.			Szt.	72306		Szt.	72144	